


CX 'HINGED' VERTICAL PLATE LIFTING CLAMPS

No specialist tools are required to repair clamps. Heat may be required to release the bonding compound on some screws.

After repair use STUDLOCK on all screws removed.

Always quote clamp serial number, part description and model when ordering spares.



Item	Description	CX1500	CX3000	CX6000
10	Shell welded assembly	N4300001688	N4300001707	N4300001790
20	Internal assy. c/w spring	N59000349	N59110320	N4300001439
27	Spring only	N59000345	N59110107	N59210318
32	Fork pin	N4300008320	N4300004399	N4300008459
34	Fork	N4300001704	N4300001692	N4300008457
35	Eye cam	N4300001693	N4300001758	N4300001850
37	Pivot bolt and nut	N4300004819	N4300001841	N4300008460
40	Cam assembly	N4300002063	N4300001049	N59210315
50	Pad assembly	N59000346	N59110315	N59210334
60	Jaw bolt assembly	N59000347	N59110136	N4300008458
71**	Master link	N4300008508	N4300008515	N4300008581
72**	Connecting link	N4300008509	N4300008516	N4300008582

****Not shown in exploded diagram**