


92 SERIES VERTICAL PLATE LIFTING CLAMPS

No specialist tools are required to repair clamps. Heat may be required to release the bonding compound on some screws.

After repair use STUDLOCK on all screws removed.

Always quote clamp serial number, part description and model when ordering spares.



Item	Description	92-500	92-1500	92-2000	92-3000
10	Shell plates (set of 4)	N59110281	N4300001258	N4300001265	N4300001272
16	Shell pins (set of 3*)	N59110289	N4300001263	N4300001274	N4300001274
17	Shell screws (6 off)	N59000562	N4300001264	N4300001275	N4300001275
20	Internal assy. c/w spring	N59110285	N59210356	N59210376	N59210376
27	Spring only	N59110290	N59210362	N59210382	N59210382
30	Hook ring & pin	N59110283	N59110202	N59110222	N59000366
40	Cam assembly	-	N59000737	N59000285	N4300001268
50	Pad assembly	N59110286	N59210357	N4300001022	N59210377
60**	Jaw bolt assembly	N59110287	-	-	-

*Set of 2 on 92-500 **Not shown in exploded diagram