


CY 'HINGED' VERTICAL PLATE LIFTING CLAMPS

No specialist tools are required to repair clamps. Heat may be required to release the bonding compound on some screws.

After repair use STUDLOCK on all screws removed.

Always quote clamp serial number, part description and model when ordering spares.



Item	Description	CY1	CY2	CY3
10	Shell plates (set of 4)	N4300001276	N4300001283	N4300001285
16	Shell pins (2) each	N4300004902	N4300001288	N4300001288
17	Shell screws (set of 4)	N4300008258	N4300008317	N4300008317
20	Internal assy. c/w spring	N59210356	N59210376	N59210376
27	Spring only	N59210362	N59210382	N59210382
30	Hook ring fork & pin	N59210354	N59210374	N59210374
35	Swivel hook ring	N59210353	N59210373	N59210373
37	Eye bolt and nut	N59210361	N59210381	N59210381
40	Cam assembly	N59000737	N59000285	N4300001268
50	Pad assembly	N59110286	N59210377	N59210377
60	Jaw bolt assembly	N4300001279	N4300001286	N4300001286